

FAC 1122 ROTARY-WING TAXIWAY, SURFACED

FY24 SUC:	\$3.24 / SY
Source:	Inflated from previous FY using ENR labor and material cost indices to measure actual inflation
Original Source:	Air Force Civil Engineer Center (AFCEC) study, 2019, which updated the cost associated with airfield pavement maintenance and repair, marking, rubber removal, etc.