

FAC 8524 Sidewalk and Walkway

RUC: \$32.42 SY

Source: Marshall and Swift 66/1, December 2007; adjusted for location and inflation using Marshall and Swift Section 99.
In V12, Tri-Service and USACE PAX Newsletter values were updated while all other values were inflated only.

Calculation follows:

SUC: \$0.00 SY

Source: Zero value.
Original Source: R.S. Means CostWorks model as follows:

8524 Sidewalk - M&S, 66/1, Dec 07	
4" thick	\$3.96 sf
	\$35.64 sy
Cost adjustment factor Dec 07 - July 08	\$1.02
	\$36.35

CostWorks 2006 Quarter 2 - FAC 8524 Sidewalk

Life = 28

UM = 1 SY

Qty	Assembly Number	Description	Frequency	Unit	Total Incl. O&P	Zip Code Prefix	Type	Release	Life / Frequency	L/F Truncated	Cost
3.000	G2033 140 0100	Remove and replace concrete sidewalk, 4' wide	30	L.F.	85.56	200	FMR	2006 Qtr 2	0.93333333	0	\$0.00
					\$85.56						\$0.00
		Preventive Maintenance	0	0							\$0.00
		Total									\$0.00
		Per Year									\$0.00
		Per Year Per SY (LF represents standard 4 ft wide sidewalk)									\$0.00